

## REPORT OF INSPECTION MOTORIZED OF VALVE

Certificate No. : 0917-24-HI-CAL-10J

### Customer Information

Company Name PT. Bhumi Jati Power  
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah  
Contract No. C-BJP-24-0014-OTH

### Instrument Information

|                        |  |                 |            |
|------------------------|--|-----------------|------------|
| KKS No.                | 60LCH31AA210                           | Power Supply    | 380 VAC    |
| Instrument Description | HP HTR 6B DRAIN CONDR COLLECTION VALVE | Stroke          | 30 mm      |
| Manufacture            | ROTORK                                 | Inspection Date | 12-05-2024 |
| Model                  | 1Q25F14B4                              |                 |            |
| Serial Number          | NT38302601                             |                 |            |
| Instrument Location    | TURBINE 1ST FLOOR                      |                 |            |

### Environment Condition

Temperature 31.9 °C  
Humidity 33 % RH

### Traveling Time

Open to Close 152.61 s  
Close to Open 153.47 s

### Stroke Result

| Command | Local | Stroke | DCS FB |
|---------|-------|--------|--------|
| [%]     | [%]   | [mm]   | [%]    |
|         |       |        |        |
|         |       |        |        |
|         |       |        |        |
|         |       |        |        |
|         |       |        |        |

| Command | Feedback |       |      |       |
|---------|----------|-------|------|-------|
|         | Local    |       | DCS  |       |
|         | Open     | Close | Open | Close |
| Close   | -        | OK    | -    | OK    |
| Open    | OK       | -     | OK   | -     |

### Visual Inspection

|                     |                                     |    |                          |        |                   |                                     |    |                          |        |
|---------------------|-------------------------------------|----|--------------------------|--------|-------------------|-------------------------------------|----|--------------------------|--------|
| Leak Check          | <input checked="" type="checkbox"/> | OK | <input type="checkbox"/> | Not OK | Tightness Check   | <input checked="" type="checkbox"/> | OK | <input type="checkbox"/> | Not OK |
| Corrosion Condition | <input checked="" type="checkbox"/> | OK | <input type="checkbox"/> | Not OK | Accessories Check | <input checked="" type="checkbox"/> | OK | <input type="checkbox"/> | Not OK |
| Gearbox Condition   | <input checked="" type="checkbox"/> | OK | <input type="checkbox"/> | Not OK |                   |                                     |    |                          |        |

### Remark

Open - Close : 700 mm

### Test Equipment

| Description                  | Serial Number | Certificate Number | Calibration Date |
|------------------------------|---------------|--------------------|------------------|
| Digital Multimeter Fluke 87V | 16230349      | S. 22 008 274      | 08-07-2022       |
| STOPWATCH CASIO              | J011Q03       | S. 23 004 599      | 27-03-2023       |

### Inspection Method

0007/SOP\_BJS/2023  
Procedure of Inspection Pneumatic and MOV

This certificate comprise of 1 page  
Date of issue, 13-05-2024

Customer Signature,



Ayrtan Humardani Putradhi

HERVITAMA  
Approved Signatory,



M. Taufiq Nur Fitriyan  
INDONESIA

Calibrated by,



Suryo Wicaksono

Sertifikat ini berlaku untuk alat dengan nama, merek dan tipe / nomor seri yang dinyatakan diatas

*This certificate applies only for the item specified above*

Dilarang mengutip, memperbanyak dan / atau mempublikasikan isi sertifikat ini tanpa izin dari PT. Hervitama Indonesia

*It is prohibited to copy, reproduce and / or publish the content of this Certificate without PT Hervitama Indonesia's approval*

\*Sertifikat ini sah bila dibubuhi cap PT. Hervitama Indonesia dan ditandatangani oleh pejabat yang berwenang

*This certificate is valid if it has approved and signed by authorized person*

