



# Report of Inspection

## Vibration Sensor

Report No. : 0281-23-HI-CAL-10

### Customer Information

Company Name PT. Bhumi Jati Power  
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah  
Contract No. C-BJP-23-0008-OTH

### Instrument Information

KKS No. 50LAY10CG013 Inspection Date 15-05-2023  
Instrument Description BFPT A THRUST BEARING POSITION 3  
Manufacture SHINKAWA  
Model FL-602F18L-M1-00-05-10  
Serial Number TASL 0031  
Instrument Location Turbin Lt. 1

### Environment Condition

Temperature 26 °C  
Humidity 63 % RH

### Inspection Result

#### Visual Inspection

Cabel Tightness	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK
Cable Condition	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK
Mounting	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK
Phisical Condition	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK

#### Healthiness

Good

#### Measurement

V - Supply	- 25.39
V - Out	- 07.86
Resistance [ $\Omega$ ]	04.03

### Remark

### Test Equipment

Description	Serial Number	Certificate Number	Calibration Date
TRUE RMS MULTIMETER	160403244	S. 21 011 088	05-10-2021

### Inspection Method

0006/SOP\_BJS/2023  
Procedure of Inspection Vibration

This certificate comprise of 1 page  
Date of Issue, 16-05-2023

Customer Signature,

Ayrton Humardani Putradhi

HERVITAMA  
Approved Signatory,

Arief Indonesia

Calibrated by,

Saiful Anam

**PT. HERVITAMA INDONESIA**

ELECTRICAL - INSTRUMENTATION - ENGINEERING

Puri Indah DA - 18 Sidoarjo 61224, Telp. (031) 8073636 - 39, Fax: (031) 8074269