



Report of Inspection Vibration Sensor

Report No. : 0285-23-HI-CAL-10

Customer Information

Company Name PT. Bhumi Jati Power
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah
Contract No. C-BJP-23-0008-OTH

Instrument Information

KKS No. 50LAY20CG013
Instrument Description BFPT B THRUST BEARING POSITION 3
Manufacture SHINKAWA
Model FL-602F18L-M1-00-05-10
Serial Number TASL 0034
Instrument Location Turbin Lt. 1

Inspection Date 15-05-2023

Environment Condition

Temperature 26 °C
Humidity 62 % RH

Inspection Result

Visual Inspection

Cabel Tightness OK
Cable Condition OK
Mounting OK
Phisical Condition OK

Not OK
 Not OK
 Not OK
 Not OK

Healthiness

Good

Measurement

V - Supply - 25.33
V - Out - 7.96
Resistance [Ω] 4.03

Remark

Test Equipment

Description	Serial Number	Certificate Number	Calibration Date
TRUE RMS MULTIMETER	160403244	S. 21 011 088	05-10-2021

Inspection Method

0006/SOP_BJS/2023
Procedure of Inspection Vibration

This certificate comprise of 1 page
Date of issue, 16-05-2023

Customer Signature,

Ayrton Humardani Putradhi

HERVITAMA
Approved Signatory,

Arief Gunawan
INDONESIA

Calibrated by,

Saiful Anam

PT. HERVITAMA INDONESIA

ELECTRICAL - INSTRUMENTATION - ENGINEERING

Puri Indah DA - 18 Sidoarjo 61224, Telp. (031) 8073636 - 39, Fax: (031) 8074269