



Report of Inspection

Vibration Sensor

Report No. : 0276-23-HI-CAL-10

Customer Information

Company Name PT. Bhumi Jati Power
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah
Contract No. C-BJP-23-0008-OTH

Instrument Information

KKS No. 50MAY10CG003
Instrument Description THRUST BEARING POSITION 2
Manufacture SHINKAWA
Model FL-602F18L-M1-00-05-10
Serial Number T9SJ0257
Instrument Location Turbin Lt. 3

Inspection Date 19-05-2023

Environment Condition

Temperature 31 °C
Humidity 61 % RH

Inspection Result

Visual Inspection

Cabel Tightness OK
Cable Condition OK
Mounting OK
Physical Condition OK

Not OK
 Not OK
 Not OK
 Not OK

Healthiness

Good

Measurement

V - Supply - 25.40
V - Out - 09.14
Resistance [Ω] 4.1

Remark

Test Equipment

| Description | Serial Number | Certificate Number | Calibration Date |
|---------------------|---------------|--------------------|------------------|
| TRUE RMS MULTIMETER | 160403244 | S. 21 011 088 | 05-10-2021 |

Inspection Method

0006/SOP_BJS/2023
Procedure of Inspection Vibration

This certificate comprise of 1 page
Date of issue, 20-05-2023

Customer Signature,

Ayrtan Humardani Putradhi

HERVITAMA

Approved Signatory,

Arief Gunawan

Calibrated by,

Abdul Latif

PT. HERVITAMA INDONESIA

ELECTRICAL - INSTRUMENTATION - ENGINEERING

Puri Indah DA - 18 Sidoarjo 61224, Telp. (031) 8073636 - 39, Fax: (031) 8074269