



Report of Inspection

Vibration Sensor

Report No. : 0253-23-HI-CAL-10

Customer Information

Company Name PT. Bhumi Jati Power
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepra - Jawa Tengah
Contract No. C-BJP-23-0008-OTH

Instrument Information

KKS No. 50MAY10CY004
Instrument Description BEARING NO.2 VIBRATION Y
Manufacture SHINKAWA
Model FL-202F08A-M2-00-05-10
Serial Number T9SH5262
Instrument Location Turbin Lt. 3

Inspection Date 19-05-2023

Environment Condition

Temperature 31 °C
Humidity 61 % RH

Inspection Result

Visual Inspection

| | | |
|--------------------|---|----|
| Cabel Tightness | ✓ | OK |
| Cable Condition | ✓ | OK |
| Mounting | ✓ | OK |
| Physical Condition | ✓ | OK |

| | |
|--|--------|
| | Not OK |
| | Not OK |
| | Not OK |
| | Not OK |

Healthiness

Good

Measurement

| | |
|-------------------------|---------|
| V - Supply | - 25.43 |
| V - Out | - 08.87 |
| Resistance [Ω] | 8.8 |

Remark

Test Equipment

| Description | Serial Number | Certificate Number | Calibration Date |
|---------------------|---------------|--------------------|------------------|
| TRUE RMS MULTIMETER | 160403244 | S. 21 011 088 | 05-10-2021 |

Inspection Method

0006/SOP_BJS/2023
Procedure of Inspection Vibration

This certificate comprise of 1 page
Date of issue, 20-05-2023

Customer Signature,

Ayrton Humardani Putradhi

HERVITAMA
Approved Signatory,

INDONESIA
Arief Gunawan

Calibrated by,

Abdul Latif

PT. HERVITAMA INDONESIA

ELECTRICAL - INSTRUMENTATION - ENGINEERING

Puri Indah DA - 18 Sidoarjo 61224, Telp. (031) 8073636 - 39, Fax: (031) 8074269