



Report of Inspection

Vibration Sensor

Report No. : 0244-23-HI-CAL-10

Customer Information

Company Name PT. Bhumi Jati Power
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah
Contract No. C-BJP-23-0008-OTH

Instrument Information

KKS No. 50LAY10CY023 Inspection Date 15-05-2023
Instrument Description BFPT A BEARING NO.2 VIBRATION X
Manufacture SHINKAWA
Model FL-202F08A-M2-00-05-10
Serial Number TASH 5366
Instrument Location Turbin Underground

Environment Condition

Temperature 26 °C
Humidity 63 % RH

Inspection Result

Visual Inspection

Cabel Tightness	✓	OK		Not OK
Cable Condition	✓	OK		Not OK
Mounting	✓	OK		Not OK
Physical Condition	✓	OK		Not OK

Healthiness

Good

Measurement

V - Supply	- 25.45
V - Out	- 08.75
Resistance [Ω]	9.0

Remark

Test Equipment

Description	Serial Number	Certificate Number	Calibration Date
TRUE RMS MULTIMETER	160403244	S. 21 011 088	05-10-2021

Inspection Method

0006/SOP_BJS/2023
Procedure of Inspection Vibration

This certificate comprise of 1 page
Date of issue, 16-05-2023

Customer Signature,

Ayrtan Humardani Putradhi

HERVITAMA
Approved Signatory,

Arief Indrawati

Calibrated by,

Saiful Anam