



Report of Inspection Vibration Sensor

Report No. : 0248-23-HI-CAL-10

Customer Information

Company Name PT. Bhumi Jati Power
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah
Contract No. C-BJP-23-0008-OTH

Instrument Information

KKS No. 50LAY20CY023 Inspection Date 15-05-2023
Instrument Description BFPT B BEARING NO.2 VIBRATION X
Manufacture SHINKAWA
Model FL-202F08A-M2-00-05-10
Serial Number TASH 5368
Instrument Location Turbin Underground

Environment Condition

Temperature 26 °C
Humidity 62 % RH

Inspection Result

Visual Inspection

Cabel Tightness	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK
Cable Condition	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK
Mounting	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK
Phisical Condition	<input checked="" type="checkbox"/>	OK	<input type="checkbox"/>	Not OK

Healthiness

Good

Measurement

V - Supply	- 25.48
V - Out	- 09.55
Resistance [Ω]	08.8

Remark

Test Equipment

Description	Serial Number	Certificate Number	Calibration Date
TRUE RMS MULTIMETER	160403244	S. 21 011 088	05-10-2021

Inspection Method

0006/SOP_BJS/2023
Procedure of Inspection Vibration

This certificate comprise of 1 page
Date of issue, 16-05-2023

Customer Signature,

Ayrton Humardani Putradhi

HERVITAMA
Approved Signatory,

Arief Gunawan

Calibrated by,

Saiful Anam

PT. HERVITAMA INDONESIA

ELECTRICAL - INSTRUMENTATION - ENGINEERING

Puri Indah DA - 18 Sidoarjo 61224, Telp. (031) 8073636 - 39, Fax: (031) 8074269