



Report of Inspection Vibration Sensor

Report No. : 0268-23-HI-CAL-10

Customer Information

Company Name PT. Bhumi Jati Power
Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah
Contract No. C-BJP-23-0008-OTH

Instrument Information

KKS No. 50MKA10CY019
Instrument Description BEARING NO.10 VIBRATION X
Manufacture SHINKAWA
Model FL-202F08L-M2-00-05-10
Serial Number T9SH5277
Instrument Location Turbin Lt. 3

Inspection Date 19-05-2023

Environment Condition

Temperature 31 °C
Humidity 61 % RH

Inspection Result

Visual Inspection

Cabel Tightness	✓	OK
Cable Condition	✓	OK
Mounting	✓	OK
Phisical Condition	✓	OK

	Not OK
	Not OK
	Not OK
	Not OK

Healthiness

Good

Measurement

V - Supply	- 25.47
V - Out	- 09.39
Resistance [Ω]	8.7

Remark

Test Equipment

Description	Serial Number	Certificate Number	Calibration Date
TRUE RMS MULTIMETER	160403244	S. 21 011 088	05-10-2021

Inspection Method

0006/SOP_BJS/2023
Procedure of Inspection Vibration

This certificate comprise of 1 page
Date of issue, 20-05-2023

Customer Signature,

Ayrtan Humardani Putradhi

HERVITAMA
Approved Signatory

Arief Gunawan

Calibrated by,

Abdul Latif

PT. HERVITAMA INDONESIA

ELECTRICAL - INSTRUMENTATION - ENGINEERING

Puri Indah DA - 18 Sidoarjo 61224, Telp. (031) 8073636 - 39, Fax: (031) 8074269