

REPORT OF INSPECTION MOTORIZED OF VALVE

Certificate No. : 0885-24-HI-CAL-10J

Customer Information

Company Name PT. Bhumi Jati Power
 Address PLTU Tanjung Jati B Unit 5&6 Tubanan, Kembang, Jepara - Jawa Tengah
 Contract No. C-BJP-24-0014-OTH

Instrument Information

KKS No. 60LAC12AA804 Power Supply 380 VAC
 Instrument Description BFPT B EXHD DRAIN VALVE Stroke 20 mm
 Manufacture ROTORK
 Model 1Q12F10A Inspection Date 10-05-2024
 Serial Number NT38303601
 Instrument Location TURBINE 1ST FLOOR

Environment Condition

Temperature 31.7 °C Traveling Time
 Humidity 38 % RH Open to Close 12.91 s
 Close to Open 13.25 s

Stroke Result

Command	Local	Stroke	DCS FB
[%]	[%]	[mm]	[%]

Command	Feedback			
	Local		DCS	
	Open	Close	Open	Close
Close	-	OK	-	OK
Open	OK	-	OK	-

Visual Inspection

Leak Check OK Not OK Tightness Check OK Not OK
 Corrosion Condition OK Not OK Accessories Check OK Not OK
 Gearbox Condition OK Not OK

Remark

OPEN = 20mm

Test Equipment

Description	Serial Number	Certificate Number	Calibration Date
FIK-87-V MULTIMETER	16230349	S. 22 008 274	08-07-2022
STOPWATCH CASIO	J011Q03	S. 23 004 599	27-03-2023

Inspection Method

0007/SOP_BJS/2023
 Procedure of Inspection Pneumatic and MOV

This certificate comprise of 1 page
 Date of issue, 11-05-2024

Customer Signature,


 Ayrton Humardani Putradhi

Approved Signatory,


 M. Taufiq Nur Fitriyani

Calibrated by,


 Suryo Wicaksono

Sertifikat ini berlaku untuk alat dengan nama, merek dan tipe / nomor seri yang dinyatakan diatas
 This certificate applies only for the item specified above
 Dilarang mengutip, memperbanyak dan / atau mempublikasikan isi sertifikat ini tanpa izin dari PT. Hervitama Indonesia
 It is prohibited to copy, reproduce and / or publish the content of this Certificate without PT Hervitama Indonesia's approval
 *Sertifikat ini sah bila dibubuhi cap PT. Hervitama Indonesia dan ditandatangani oleh pejabat yang berwenang
 This certificate is valid if it has approved and signed by authorized person

